

**TERMS AND CONDITIONS FOR APPLYING TO SIPLAST CERTIFIED  
APPLICATOR AND CERTIFIED SUPERVISOR CARDS**

#### **A. REQUIREMENTS FOR APPROVAL**

Applicators and Supervisors must meet the following requirements to get approved by Siplast:

- 1- Be an employee of a waterproofing company. Temporary workers are not admitted. In case of subcontractors, the approval is valid only for jobs contracted by the Siplast customer.
  
- 2- Possess the necessary tools to apply materials:
  - Torch (fire / hot air)
  - Cutter
  - Safety clothing
  - Trowel
  - Measuring tape
  - Pressure roller
  
- 3- Personal participation in the training provided by Siplast, to both theoretical and practical courses, and further follow-up and validation of the acquired skills.

#### **B - OBTAINING THE APPROVAL**

If the request is consistent, Siplast will recognize the approval for the applicant Company issuing the related certified card.

The approval is granted for a maximum period of 2 years, with 31<sup>st</sup> December as the expiration date. After this period, the company, if still interested, will renew the request for approval within the same existing conditions.

#### **C - LOSS OF APPROVAL**

The approval can be withdrawn for any of the following reasons:

- 1) Termination of the employment contract with the Company registered on the certified Applicator or Supervisor card.
- 2) For repeated misapplications in the execution of works.
- 3) For permanent breach of the requested conditions.
- 4) For debt of the approved Company towards Siplast/Icopal.